

From: [ANDERSON Jim M](#)
To: [Eric Blischke/R10/USEPA/US@EPA](#)
Subject: RE: FW: FS Matrix
Date: 09/29/2009 10:19 AM

OK

-----Original Message-----

From: Blischke.Eric@epamail.epa.gov [mailto:Blischke.Eric@epamail.epa.gov]
Sent: Tuesday, September 29, 2009 10:18 AM
To: Fuentes.Rene@epamail.epa.gov
Cc: ANDERSON Jim M; blischke.eric@epa.gov; Humphrey.Chip@epamail.epa.gov;
Koch.Kristine@epamail.epa.gov
Subject: Re: FW: FS Matrix

We will set up the TCT number - 800-504-8071; 3758297.

Eric

Rene	
Fuentes/R10/USEP	
A/US	To
09/29/2009 09:06	"ANDERSON Jim M"
AM	<ANDERSON.Jim@deq.state.or.us>
	cc
	Humphrey.Chip@epamail.epa.gov,
	blischke.eric@epa.gov, Kristine
	Koch/R10/USEPA/US@EPA
	Subject
	Re: FW: FS Matrix(Document link:
	Eric Blischke)

Can you send me the phone number to call in? I will not be going down today, but will call in for the meeting.

Thanks, Rene

René Fuentes P.E., P.HG.
Hydrogeologist
Office of Environmental Assessment
USEPA Region 10 (OEA-095)
1200 Sixth Ave., Suite 900
Seattle, WA 98101

phone: (206) 553-1599

"ANDERSON
Jim M"
<ANDERSON.
Jim@deq.st
ate.or.us>

09/23/2009
03:41 PM

To
"THIESSEN Kenneth" <THIESSEN.Kenneth@deq.state.or.us>,
"ORR Jim" <orr.jim@deq.state.or.us>, "GAINER Tom"
<GAINER.Tom@deq.state.or.us>, "RAPP Shawn"
<RAPP.Shawn@deq.state.or.us>, "ROMERO Mike"
<ROMERO.Mike@deq.state.or.us>, "PUGH Mark"
<PUGH.Mark@deq.state.or.us>, "BAYUK Dana"
<BAYUK.Dana@deq.state.or.us>, "MCCLINCY Matt"
<Matt.Mcclincy@state.or.us>, "MANZANO Scott"
<MANZANO.Scott@deq.state.or.us>, "LACEY David"
<LACEY.David@deq.state.or.us>, "TARNOW Karen E"
<TARNOW.Karen@deq.state.or.us>, "SUTTER Jennifer"
<SUTTER.Jennifer@deq.state.or.us>

cc

Eric Blischke/R10/USEPA/US@EPA, Chip
Humphrey/R10/USEPA/US@EPA, Kristine
Koch/R10/USEPA/US@EPA, Rene Fuentes/R10/USEPA/US@EPA
Subject
FW: FS Matrix

Good afternoon, everyone!

We had our 2nd DEQ/EPA Portland Harbor FS Matrix meeting yesterday. The meeting went well, & I think our DEQ PMS really shined. You all came to the meeting prepared & were able to answer all the questions we posed. Thanks!

After the meeting EPA, Matt & I talked about how we could better focus your preparation & our meeting format to be more efficient. I think we could be a little more efficient by adding a little more structure to both your preparation & the meetings. With that in mind..., I'd like you to focus your preparation on the following specific questions:

- 1) What are the upland COIs? What are the general levels of the most significant upland contamination relative to JSCS SLVs (10x, 100x, 1000x, etc)?
- 2) What are the upland sources (e.g., tank release, facility operations, etc)?
- 3) What are the current or reasonably likely future contaminant migration pathways linking the uplands to the river (e.g., GW, stormwater, bank erosion, etc)?
- 4) What's the relative recontamination potential of upland sources? i.e., if an effective source control measure is not implemented for a complete contaminant migration pathway (e.g., GW plume), will that pathway likely result the recontamination of a future in-river remedy (e.g., cap)?
- 5) What's the current & anticipated future land use of the facility & sites surrounding the facility?
- 6) Are there active over-water structures (e.g., docks, wharfs), & is it anticipated these structures will be used in the future?
- 7) Are there any under-river utility crossings in the area? Are there any subsurface sediment obstructions (e.g., buried ships, hard pan, shallow bedrock, etc)?
- 8) What is the general schedule for completing the phase(s) of source control?

During the upcoming meetings, we'll try to stick to addressing these questions.

Next meeting is scheduled for Tues 9/29 starting at 1:30 in Room E. There may be a possibility of starting at 1:00 if I can talk the person who has it reserved over the lunch hour to give it up..., I'll let you know if that happens. In the 9/29 meeting we'll go over:

- 1) AOPC 13- Willamette Cove (Ken T);
- 2) AOPC 15- M&B (Scott M)
- 3) AOPC 16- Willbridge (Mike R)
- 4) AOPC 17- Triangle Park (Jim A & EPA), Portland Shipyard (Dave), & Fred Devine (Karen T)

If we have time, we may also want to squeeze in AOPC 6- Terminal 4 (Tom G & Jim A).

Thanks, again, everyone!
Jim

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

"MCCLINCY
Matt"
<MCCLINCY.M
att@deg.sta
te.or.us>

Eric Blischke/R10/USEPA/US@EPA, Chip
Humphrey/R10/USEPA/US@EPA, Kristine
Koch/R10/USEPA/US@EPA

To

09/17/2009
03:58 PM

"ANDERSON Jim M" <ANDERSON.Jim@deg.state.or.us>,
"THIESSEN Kenneth"
<THIESSEN.Kenneth@deg.state.or.us>, "ORR Jim"
<orr.jim@deg.state.or.us>, "GAINER Tom"
<GAINER.Tom@deg.state.or.us>, "RAPP Shawn"
<RAPP.Shawn@deg.state.or.us>, "ROMERO Mike"
<ROMERO.Mike@deg.state.or.us>

CC

Subject

FS Matrix - September 22 Meeting

All,

DEQ will be prepared to discuss AOPCs 2, 3, 4 and 5 at the September 22

nd meeting. We have room A/B scheduled at the DEQ NWR office on the 4th floor from 1 to 5.

Matt McClincy

Oregon Department of Environmental Quality

Northwest Region

2020 SW Fourth Ave., Suite 400

Portland, Oregon 97201-4987

Phone 503-229-5538

Fax 503-229-6945